



ASSEMBLY INSTRUCTION

1. INSERT UPRIGHT (B) INTO BASE (A), INSERT ITEM (F) INTO HOLE ON ITEM (B) THEN PLACE BEARING (G);
2. SLIDE SPINNER RACK (D) FROM TOP OF UPRIGHT POLE (B) TO RIGHT LOCATION;
3. INSERT END CAP (C) INTO UPRIGHT (B);
4. INSERT SIGN HOLDER (E) INTO END CAP (C).

PAPTS LIST

1	BASE (A)
1	UPRIGHT (B)
1	END CAP (C)
1	SPINNER RACK (D)
1	SIGN HOLDER (E)
1	PIN (F)
1	BEARING (G)