



ASSEMBLY INSTRUCTION

1. INSERT BOTTOM POLE (B) INTO BASE (A) AND TIGHTEN SCREW.
2. SCREW MIDDLE POLE (C) INTO BOTTOM POLE (B).
3. SCREW TOP POLE (D) ONTO MIDDLE POLE (C).
4. SLIDE THE METAL RING (E) ONTO POLE AT DESIRED HEIGHT & TIGHTEN SET SCREWS. SLIDE HAT HOLDER (F) OVER THE POLE UNTIL IT RESTS SECURELY ON THE METAL RING.
5. SLIDE METAL RING (E) ONTO POLE & SECURE JUST ABOVE HAT HOLDER.
6. REPEAT STEPS 4 & 5 FOR THE REST OF HAT HOLDERS (F).
7. INSERT FINAL (G) INTO TOP POLE (D).

PARTS LIST	
1	BASE (A)
1	BOTTOM POLE (B)
1	MIDDLE POLE (C)
1	TOP POLE (D)
10	METAL RING (E)
5	HAT HOLDER (F)
1	FINIAL (G)