



ASSEMBLY INSTRUCTION

1. ASSEMBLE THE BASE WHICH CONSISTS OF THE HUB(B)AND 5 LEGS(A) . INSERT LEG INTO HUB.
2. SCREW BOTTOM POLE(C)ONTO THE BASE.
3. INSERT THE PIN(I)THROUGH THE HOLE OF BOTTOM POLE(C) . SLIDE BEARING(F) OVER THE POLE UNTIL IT RESTS ON PIN.
4. SCREW TOP POLE(D)ONTO THE BOTTOM POLE(C) .
5. LOCATE SPINNER POCKET. SLIDE IT ONTO THE BOTTOM POLE AND TOP POLE.
6. INSERT END CAP(G)INTO TOP POLE(D) . INSERT SIGN HOLDER (H) INTO THE HOLE OF END CAP(G) .

PARTS LIST		
ITEM	DESCRIPTION	QTY
A	LEG	5
B	HUB	1
C	BOTTOM POLE	1
D	TOP POLE	1
E	SPINNER	1
F	BEARING	1
G	END CAP	1
H	SIGN HOLDER	1
I	PIN	1